




Notes: **DETAIL FOR BELOW GROUND INLET PIPE**

Side View

Gable View



|  |   |           |           |              |
|--|---|-----------|-----------|--------------|
| <br>GREASE TRAP MAINTENANCE · COMPLIANCE<br><br>Tel: 1890 336633<br>Email: info@taylormade.ie | TITLE:<br>Installation Guide for Underground <b>BIOTRAP® 9520</b> | DRAWN BY: | SCALE:    |              |
|  | CLIENT: Grantstown Proiry Care Centre                             | DATE:     | MATERIAL: | APPROVED BY: |